ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	**Street Name**	**Significant Landmark**
W0098, W0177, W0100, W0102, W0104, W0096	NA	Navya Nagara
Segment No.	**Total Length (m)**	
7/S-W0098/S024145	896.37	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	57.79	77.603403	13.074145	77.603274	13.073638	4th Cross	2nd Cross
2	188.37	77.602426	13.073784	77.604122	13.073413	2nd Cross	Dead End
3	185.72	77.602512	13.074056	77.604186	13.073701	3rd Cross	Dead End
4	182.70	77.602604	13.074348	77.604245	13.073977	4th Cross	Dead End
5	181.05	77.602705	13.074699	77.604336	13.074348	5th Cross	Dead End
6	100.74	77.603558	13.074881	77.604465	13.074683	6th Cross	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads of Navyanagara in Ward No 07, Byatarayanapura	3000000	2017-18
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Road	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	1.Providing and Laying BC.	007-18-000042
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/100/17-1	02/03/2018	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
25/09/2018	24/09/2018	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s Executive Engineer, K.R.I.D.L		0.00
Phone No.	**E-Mail ID**	

9449863065

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Pushpalatha.N.D
Date of Inspection	**Remarks**	
18/12/2018		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Zone: YELAHANKA Ward No: 7 Ward Name: Byatarayanapura Street ID: W0098, W0177, W0100, W0102,

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.R.L.Parameshwaraiah	05/01/2019	17/01/2019	Approved
SE	Basavaraj R Kabade	05/01/2019	17/01/2019	Forwarded
EE	Mohandas H.T	05/01/2019	17/01/2019	completed
AEE	H.Ranganath	18/12/2018	17/01/2019	Verified
AE	Pushpalatha.N.D	18/12/2018	17/01/2019	Mobile Verification Done
AE	Pushpalatha.N.D	18/12/2018	17/01/2019	Forwarded

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0098, W0177, W0100, W0102,

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	**Street Name**	**Significant Landmark**
W0106, W0181, W0179, W0108	NA, Vinayaka Lyt 3rd Crs, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	Navya Nagar
Segment No.	**Total Length (m)**	
7/C-W0106/S030737	406.93	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	43.92	77.603529	13.073204	77.603465	13.072812	1st B Cross	Dead End
2	38.90	77.603827	13.073136	77.603757	13.072791	1st A Cross	Dead End
3	130.45	77.602223	13.073089	77.603231	13.073220	1st C Cross	Dead End
4	193.66	77.604068	13.073136	77.602303	13.073403	1st Cross	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
improvements to roads of Navyanagara in Ward No 07, Byatarayanapura	3000000	2017-18
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Road	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	1. Providing and Laying BC.	007-18-000042
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/100/17-18	02/03/2018	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
25/09/2018	24/09/2020	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s Executive Engineer, K.R.I.D.L		0.00
Phone No.	**E-Mail ID**	
9449863065		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Pushpalatha.N.D
Date of Inspection	**Remarks**	
18/12/2018		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.R.L.Parameshwaraiah	05/01/2019	17/01/2019	Approved
SE	Basavaraj R Kabade	05/01/2019	17/01/2019	Forwarded
EE	Mohandas H.T	05/01/2019	17/01/2019	completed
AEE	H.Ranganath	18/12/2018	17/01/2019	Verified

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0106, W0181, W0179, W0108

AE	Pushpalatha.N.D	18/12/2018	17/01/2019	Mobile verification Done
AE	Pushpalatha.N.D	18/12/2018	17/01/2019	Forwarded

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0106, W0181, W0179, W0108